

Back Lane Car Park Walk Round Risk Assessment

14 March 2018

The car park is in generally good condition and the recommendations of the previous report have been carried out successfully. The following areas noted below for monitoring:

A pothole needs to measure a minimum of 30mm depth X 300mm diameter to be considered hazardous. Smaller defects do cause accidents, but the law tends not to hold councils responsible.

The water and electrical points have been checked and secured.



There is some wear and tear to the car park surface and the overflow car park which should be monitored. The worst is right at the entrance.



RECOMMENDATION: No action needed at this time.

the grit bin is slightly worse.



RECOMMENDATION: To be monitored but no action needed at this time.